


General Information

Date & Time: 10, Apr, 2025 14:50

Make	Toyota	Model	Vios
YOM	2020	Mileage	42,823
Registration No.	NGO1096	Chassis No.	PA1B18F33L4118535
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	126	112	125
2	Boot Lid	118.0	122	114	118
3	Roof	108.5	117	106	108/103
4	Left Front Fender	102.6	106	102	100
5	Left Front Door	111.0	108	113	112
6	Center Panel Left				
7	Left Rear Door	110.3	116	112	103
8	Left Back Panel	118.3	123	116	116
9	Right Front Fender	107.6	103	108	112
10	Right Front Door	105.3	104	108	104
11	Center Panel Right				
12	Right Rear Door	109.6	103	110	116
13	Right Back Panel	117.6	118	109	126

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / Steering Wheel - Worn, Peel, Crack - Large / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Front Door, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate and Jack, Incomplete tools, with rim no tire. no warranty booklet, scratches on tail lights