

General Information

Date & Time: 23, Apr, 2025 18:13

Make	Toyota	Model	Vios
YOM	2025	Mileage	5,248
Registration No.	NHS5747	Chassis No.	PA1B18F33R4262983
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	91.7	95	86	95
2	Boot Lid	90.9	91	90	93
3	Roof	89.2	95	86	89/88
4	Left Front Fender	86.1	90	84	84
5	Left Front Door	87.7	89	86	89
6	Center Panel Left				
7	Left Rear Door	87.6	96	89	78
8	Left Back Panel	94.2	96	96	91
9	Right Front Fender	88.0	88	87	89
10	Right Front Door	93.2	91	95	95
11	Center Panel Right				
12	Right Rear Door	89.8	85	91	94
13	Right Back Panel	93.1	90	90	100

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Small	Remarks (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet/ with spare tire and jack/ with LTO plate/ incomplete tools/ power steering issue due to weak battery