

General Information

Date & Time: 24, Jul, 2025 12:13

Make	Toyota	Model	Rush
YOM	2023	Odo Meter Reading	33,393
Registration No.	NHC6089	Chassis No.	MHKE8FF3PNK050432
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.7	103	64	76
2	Boot Lid	90.1	93	86	92
3	Roof	96.3	88	93	106/98
4	Left Front Fender	121.3	134	124	106
5	Left Front Door	207.6	272	160	191
6	Center Panel Left				
7	Left Rear Door	106.6	108	110	102
8	Left Back Panel	98.4	101	93	101
9	Right Front Fender	100.2	100	103	98
10	Right Front Door	101.2	104	100	100
11	Center Panel Right				
12	Right Rear Door	98.8	97	100	100
13	Right Back Panel	92.0	96	85	95

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small / Steering Wheel - Worn, Peel, Crack - Medium / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p>Remarks (L) Front Door - Repair Traces - Yes / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Roof - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Low Battery. Temperature switch of aircon issue. GR body kit at rear bumper has small crack right side. With warranty booklet, spare tire, jack, tools and seat cover. 1 key. With LTO plate.</p>