


General Information

Date & Time: 31, Jul, 2025 13:02

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	2,716
Registration No.	CCP2193	Chassis No.	MHFAABY2S0038394
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	106	110	112
2	Boot Lid	99.5	100	108	91
3	Roof	113.7	128	118	104/105
4	Left Front Fender	102.4	103	99	105
5	Left Front Door	116.3	109	115	125
6	Center Panel Left				
7	Left Rear Door	105.3	109	101	106
8	Left Back Panel	110.6	118	109	105
9	Right Front Fender	102.9	106	105	98
10	Right Front Door	110.0	117	107	106
11	Center Panel Right				
12	Right Rear Door	108.3	108	102	115
13	Right Back Panel	110.3	104	101	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / Mat Other - Grime - Small / (L) Front Floor Mat - Grime - Small / Sunvisor, Sunglass Holder - Crinkle - Medium	Remarks Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small
Frame Evaluation : C	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes

Inspector Notes

Damaged frontbumper and hood/bonnet. Left headlight issue. Left signal light issue. With warranty booklet, spare tire and jack. Without tools and seat cover. 2 keys. LTO plate not installed in this unit.