

General Information

Date & Time: 06, Aug, 2025 16:07

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	59,104
Registration No.	BAG3206	Chassis No.	PA1B18F34R4257582
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.0	111	111	120
2	Boot Lid	117.3	113	121	118
3	Roof	108.2	118	101	103/111
4	Left Front Fender	97.4	98	95	99
5	Left Front Door	106.6	102	103	115
6	Center Panel Left				
7	Left Rear Door	112.3	133	104	100
8	Left Back Panel	115.3	126	111	109
9	Right Front Fender	99.3	98	99	101
10	Right Front Door	103.5	112	99	100
11	Center Panel Right				
12	Right Rear Door	106.2	99	103	117
13	Right Back Panel	100.8	105	94	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Mat Other - Grime - Medium / (R) Front Trim - Grime - Small / Console, Switches, Vents - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Cut, Crack - Large / (L) Front Trim - Worked - Small / Ceiling - Grime - Small	Remarks Bonnet, Headlight - Repair mark - Difference in Color / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / Roof - Scratch - Small / (L) Rear Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet, with jack, no tools, with spare tire, with LTO plate, scratched and cracked tail light, headlight unit issue