


General Information

Date & Time: 07, Aug, 2025 08:11

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	11,118
Registration No.	NHN6391	Chassis No.	MHKB3FE10RK003873
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Cargo
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	60.7	54	78	51
2	Boot Lid	52.9	56	61	42
3	Roof	64.2	89	53	57/57
4	Left Front Fender	46.9	40	46	55
5	Left Front Door	52.2	60	50	47
6	Center Panel Left				
7	Left Rear Door	53.0	54	52	53
8	Left Back Panel	53.0	52	53	55
9	Right Front Fender	53.4	52	63	46
10	Right Front Door	50.6	55	49	48
11	Center Panel Right				
12	Right Rear Door	56.0	51	60	57
13	Right Back Panel	59.9	63	53	64

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Missing - Yes / Trim Other - Worked - Small / Trim Other - Worked - Small / Overall Interior - Smell - Yes / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With LTO plate and warranty booklet and Sparetire. No Tools and Jack, Scratch headlight and tail light , adhesive marks on door handle.