

General Information

Date & Time: 04, Sep, 2025 15:42

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	32,660
Registration No.	EAJ2639	Chassis No.	PA1B18F36R4255722
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	113	104	112
2	Boot Lid	115.0	111	116	118
3	Roof	99.1	103	95	97/102
4	Left Front Fender	100.0	100	101	99
5	Left Front Door	101.5	99	106	100
6	Center Panel Left				
7	Left Rear Door	106.6	109	105	106
8	Left Back Panel	113.0	120	111	108
9	Right Front Fender	169.0	165	179	163
10	Right Front Door	105.2	100	105	111
11	Center Panel Right				
12	Right Rear Door	107.0	98	113	110
13	Right Back Panel	107.0	100	102	119

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Rear Seat - Grime - Medium / Mat Other - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks (R) Front Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Dent - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
irregular VS form LTO apprehension/with LTO plate/with spare tire/with reverse camera/No warranty booklet/No spare key/with jack /No tools