

General Information

Date & Time: 10, Oct, 2025 18:23

Make	Toyota	Model	Hilux
YOM	2023	Odo Meter Reading	12,794
Registration No.	EAG3127	Chassis No.	MR0AB8DD2P5034613
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	126	128	123
2	Boot Lid	103.6	100	109	102
3	Roof	111.7	114	119	106/108
4	Left Front Fender	114.0	113	112	117
5	Left Front Door	106.6	110	107	103
6	Center Panel Left				
7	Left Rear Door	106.6	106	113	101
8	Left Back Panel	108.6	111	112	103
9	Right Front Fender	119.6	120	118	121
10	Right Front Door	108.6	106	109	111
11	Center Panel Right				
12	Right Rear Door	110.0	106	110	114
13	Right Back Panel	106.1	104	116	98

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium	Remarks Rear Gate - Dent - Small / (R) Side Gate - Scratch - Medium / (L) Rear Door, Molding - Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Side Gate - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Window (each) - Stuck, Gap - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet/ no jack and tools/ with spare tire and LTO plate