

General Information

Date & Time: 03, Nov, 2025 19:59

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	8,684
Registration No.	GBC1735	Chassis No.	PA1B18F32P4233116
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	101	100	110
2	Boot Lid	96.5	96	94	100
3	Roof	85.6	92	87	82/81
4	Left Front Fender	87.2	91	88	83
5	Left Front Door	93.4	93	92	96
6	Center Panel Left				
7	Left Rear Door	95.0	101	95	89
8	Left Back Panel	101.6	110	98	97
9	Right Front Fender	90.4	87	92	92
10	Right Front Door	86.5	86	90	83
11	Center Panel Right				
12	Right Rear Door	93.1	95	90	94
13	Right Back Panel	97.8	93	95	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Without warranty booklet and tools. With spare tire,jack and seat cover. 1 key. LTO plate not installed.