

General Information

Date & Time: 12, Nov, 2025 15:03

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	9,297
Registration No.	CCA9962	Chassis No.	PA1B18F32R4262246
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	130	113	116
2	Boot Lid	113.6	119	103	119
3	Roof	102.5	113	99	102/97
4	Left Front Fender	101.1	101	95	107
5	Left Front Door	107.0	106	109	106
6	Center Panel Left				
7	Left Rear Door	117.6	116	113	124
8	Left Back Panel	119.6	125	113	121
9	Right Front Fender	107.0	110	104	107
10	Right Front Door	110.3	111	111	109
11	Center Panel Right				
12	Right Rear Door	112.3	115	109	113
13	Right Back Panel	123.0	130	109	130

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch, Peeled - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with warranty booklet, with jack, 1key,no spare tire, no tools, Crack head lights, Crack tail light,foul smell,possible flooded,