

General Information

Date & Time: 11, Nov, 2025 15:19

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	11,891
Registration No.	DBQ6696	Chassis No.	PA1B18F39R4269369
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	125	105	119
2	Boot Lid	110.6	110	111	111
3	Roof	96.3	101	93	92/99
4	Left Front Fender	98.9	101	98	98
5	Left Front Door	98.8	96	97	104
6	Center Panel Left				
7	Left Rear Door	106.0	115	102	101
8	Left Back Panel	108.3	116	105	104
9	Right Front Fender	106.3	107	103	109
10	Right Front Door	98.4	98	99	98
11	Center Panel Right				
12	Right Rear Door	96.8	95	94	101
13	Right Back Panel	103.9	96	106	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small	Remarks (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/No spare key/With jack and incomplete tools/with warranty booklet/with reverse camera