

General Information

Date & Time: 15, Nov, 2025 15:50

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	28,475
Registration No.	CCD3818	Chassis No.	PA1B18F36R4253856
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	106	101	107
2	Boot Lid	105.4	98	103	115
3	Roof	100.1	106	104	89/101
4	Left Front Fender	110.0	108	112	110
5	Left Front Door	165.0	165	149	181
6	Center Panel Left				
7	Left Rear Door	128.6	142	117	127
8	Left Back Panel	221.0	387	130	146
9	Right Front Fender	95.7	103	91	93
10	Right Front Door	91.9	91	87	98
11	Center Panel Right				
12	Right Rear Door	98.4	96	92	107
13	Right Back Panel	101.6	97	99	109

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small	Remarks (L) Front Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, 1key,with spare tire, no warranty booklet, no jack and tools, no trunk cover