

General Information

Date & Time: 04, Dec, 2025 13:56

Make	Toyota	Model	Hiace
YOM	2021	Odo Meter Reading	61,454
Registration No.	DAU9005	Chassis No.	JTNAFAPXM8019493
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	140.6	153	124	145
2	Boot Lid	112.6	110	114	114
3	Roof	122.7	141	127	118/105
4	Left Front Fender	187.0	195	194	172
5	Left Front Door	124.6	125	130	119
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	117.3	117	110	125
9	Right Front Fender	126.6	123	137	120
10	Right Front Door	124.6	122	128	124
11	Center Panel Right				
12	Right Rear Door	124.3	121	125	127
13	Right Back Panel	129.0	128	130	129

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes</p>	<p>Remarks (L) Front Fender - Repair Traces - Yes / Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, scratch and crack tail light and headlight, worn tires and Sparetire, No spare key, no reverse camera, foul smell, Room light and Plate light issue, HPG RECOVERED.</p>