

General Information

Date & Time: 16, Dec, 2025 09:00

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	21,755
Registration No.	NHU7625	Chassis No.	PA1B18F34R4269201
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	109	119	113
2	Boot Lid	111.3	115	106	113
3	Roof	107.2	96	100	93/140
4	Left Front Fender	99.4	98	101	99
5	Left Front Door	105.0	99	106	110
6	Center Panel Left				
7	Left Rear Door	106.9	117	104	100
8	Left Back Panel	120.6	141	115	106
9	Right Front Fender	103.5	107	100	104
10	Right Front Door	105.9	96	112	110
11	Center Panel Right				
12	Right Rear Door	107.0	104	103	114
13	Right Back Panel	106.6	98	108	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Dashboard - Worked - Minimal / Ceiling - Grime - Small / Trunk Room - Worked - Minimal / Console, Switches, Vents - Worked - Minimal	Remarks (L) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small
Frame Evaluation : B	Functional Evaluation : B
Remarks Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Battery - Weak - Yes / Head Light, High Beam - Issue - Yes

Inspector Notes

with LTO plate, with reverse camera, with spare tire, with incomplete tools & jack, with warranty booklet, with spare key, no manual booklet, issue on headlight bright, scratches on taillight, possible flooded.