

General Information

Date & Time: 08, Jan, 2026 15:56

Make	Hino	Model	XZU309LN
YOM	2025	Odo Meter Reading	1,476
Registration No.	NKP2681	Chassis No.	MJEACN4F4S5003758
CC	4.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	58.9	58	58	61
2	Boot Lid	85.7	82	85	90
3	Roof	79.2	65	68	92/92
4	Left Front Fender	62.3	53	73	62
5	Left Front Door	58.8	57	56	64
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	125.6	127	114	136
9	Right Front Fender	52.0	53	58	46
10	Right Front Door	59.2	69	54	56
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	135.6	101	168	138

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Minimal / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
No Lto plate, with spare tire, with jack and tools, 1key, no warranty booklet, aircon issue