

General Information

Date & Time: 16, Jan, 2026 10:15

Make	Toyota	Model	Fortuner
YOM	2017	Odo Meter Reading	82,683
Registration No.	NBY7060	Chassis No.	MHFGB5GS9H042799
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Pearl White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	139.6	127	148	144
2	Boot Lid	136.0	130	148	130
3	Roof	128.0	138	138	129/107
4	Left Front Fender	127.0	138	119	124
5	Left Front Door	127.0	119	122	140
6	Center Panel Left				
7	Left Rear Door	126.6	144	123	113
8	Left Back Panel	132.3	141	130	126
9	Right Front Fender	126.3	142	118	119
10	Right Front Door	126.6	128	130	122
11	Center Panel Right				
12	Right Rear Door	123.6	119	115	137
13	Right Back Panel	138.3	150	126	139

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Floor Mat - Missing - Yes	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Window (each) - Stuck, Gap - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
No Lto plate, with warranty booklet, with jack, 1key, no spare tire and tools, scratches on headlights and taillights, parking sensor missing