

General Information

Date & Time: 20, Jan, 2026 12:28

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	27,250
Registration No.	NHS1805	Chassis No.	PA1B18F37P4232415
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	118	95	103
2	Boot Lid	101.8	106	97	103
3	Roof	96.1	91	84	91/118
4	Left Front Fender	156.0	177	170	121
5	Left Front Door	99.9	100	102	98
6	Center Panel Left				
7	Left Rear Door	96.6	95	94	100
8	Left Back Panel	332.6	173	632	193
9	Right Front Fender	93.2	95	89	96
10	Right Front Door	94.3	96	95	93
11	Center Panel Right				
12	Right Rear Door	90.6	86	92	95
13	Right Back Panel	94.0	102	89	92

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/No spare tire/No spare key/No reverse camera/No jack and incomplete tools/No seat cover/No warranty booklet</p>