

General Information

Date & Time: 23, May, 2026 14:25

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	25,252
Registration No.	CCQ5175	Chassis No.	PAHACACA7S6426442
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	110	118	103
2	Boot Lid	68.3	69	68	68
3	Roof	122.7	136	126	118/111
4	Left Front Fender	111.6	106	110	119
5	Left Front Door	107.6	105	110	108
6	Center Panel Left	95.4	90	104	92
7	Left Rear Door				
8	Left Back Panel	76.0	85	74	69
9	Right Front Fender	106.5	117	109	94
10	Right Front Door	107.6	101	112	110
11	Center Panel Right	114.3	123	114	106
12	Right Rear Door				
13	Right Back Panel	79.1	78	83	76

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Worn, Scratch, Cut, Crack - Minimal / Ceiling - Grime - Minimal / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Small / Roof - Modified - Large / Rear Gate - Modified - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Side Gate - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / Cargo Bed Floor - Scratch - Large / Cab Back Panel - Modified - Large / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

No Lto plate, 1key, no warranty booklet and tools, no spare tire and jack, scratches on headlights, slippery cab bed floor