BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 23, Jul, 2026 12:18

Make	Mitsubishi	**Model**	Mirage
YOM	2026	**Odo Meter Reading**	10,702
Registration No.	NJK7017	**Chassis No.**	PAEA13RXTSA002817
CC	1.2	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**148.3**	134	160	151
2	Boot Lid	**121.6**	102	141	122
3	Roof	**110.2**	103	115	108/115
4	Left Front Fender	**121.3**	115	121	128
5	Left Front Door	**118.0**	118	116	120
6	Center Panel Left				
7	Left Rear Door	**114.6**	123	109	112
8	Left Back Panel	**124.0**	125	125	122
9	Right Front Fender	**129.3**	129	131	128
10	Right Front Door	**118.0**	116	120	118
11	Center Panel Right				
12	Right Rear Door	**195.0**	287	142	156
13	Right Back Panel	**300.6**	160	157	585

Overall Evaluation : A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Carpet - Worked - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal	**Remarks** (R) Front Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Defects not found

Inspector Notes
With Lto plate, with spare tire and jack, 2keys, no warranty booklet and tools, scratches on headlights