BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 24, Jul, 2026 15:58

Make	Toyota	**Model**	Hilux Tamaraw
YOM	2026	**Odo Meter Reading**	9,577
Registration No.	CDC5288	**Chassis No.**	PAHACACA7T6435898
CC	2.4	**Transmission**	M/T
Fuel Type	Diesel	**Type of Body**	Utility Passenger
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**104.8**	106	109	100
2	Boot Lid	**110.9**	80	96	157
3	Roof	**125.2**	131	131	119/120
4	Left Front Fender	**108.6**	106	109	111
5	Left Front Door	**112.0**	110	110	116
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	**93.7**	85	103	93
9	Right Front Fender	**103.4**	113	100	97
10	Right Front Door	**105.0**	105	104	106
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	**85.7**	77	92	89

Overall Evaluation : A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : C
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / (R) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Minimal	**Remarks** (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / Cargo Bed Floor - Scratch - Large / Cab Back Panel - Scratch - Small / Rear Gate - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes

Inspector Notes
With Lto plate, with spare tire and jack, with warranty booklet, 2keys,