BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 25, Jul, 2026 13:04

Make	Toyota	**Model**	Lite Ace
YOM	2023	**Odo Meter Reading**	12,388
Registration No.	NHJ6461	**Chassis No.**	MHKU3FE10PK003783
CC	1.5	**Transmission**	M/T
Fuel Type	Gas	**Type of Body**	Pickup
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**58.0**	57	62	55
2	Boot Lid	**43.8**	46	45	40
3	Roof	**45.5**	45	47	45/46
4	Left Front Fender	**45.3**	49	46	41
5	Left Front Door	**48.7**	42	52	52
6	Center Panel Left	**63.4**	60	58	73
7	Left Rear Door				
8	Left Back Panel	**43.0**	45	44	40
9	Right Front Fender	**62.7**	66	57	65
10	Right Front Door	**57.8**	52	61	61
11	Center Panel Right	**66.9**	74	60	68
12	Right Rear Door				
13	Right Back Panel	**42.8**	43	48	38

Overall Evaluation : C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : C	Exterior Evaluation : E
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Glove Box - Worn, Scratch, Cut, Crack - Minimal / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Large / Sunvisor, Sunglass Holder - Grime - Small / Carpet - Worked - Large / Overall Interior - Worn as per age - Yes	**Remarks** (L) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Side Gate - Modified - Medium / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Rear Gate - Scratch & Dent - Large / Cargo Bed Floor - Rust, Corrosion - Large / Cab Back Panel - Scratch - Large / (L) Side Gate - Modified - Medium / (L) Side Gate - Scratch - Large / (L) Center Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Medium / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, with spare tire and jack, 1key, no warranty booklet and tools, Crack headlight and taillight