BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 24, Jul, 2026 16:05

Make	Toyota	**Model**	Vios
YOM	2025	**Odo Meter Reading**	21,461
Registration No.	NOA7352	**Chassis No.**	PA1B18D35S4290323
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**108.6**	115	101	110
2	Boot Lid	**183.3**	188	176	186
3	Roof	**94.4**	95	96	95/92
4	Left Front Fender	**101.7**	103	106	96
5	Left Front Door	**101.3**	101	100	103
6	Center Panel Left				
7	Left Rear Door	**102.9**	105	99	105
8	Left Back Panel	**105.9**	113	110	95
9	Right Front Fender	**101.7**	102	106	97
10	Right Front Door	**100.0**	95	100	105
11	Center Panel Right				
12	Right Rear Door	**101.9**	106	99	101
13	Right Back Panel	**101.2**	94	97	113

Overall Evaluation : A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Grading Report

Interior Evaluation : A	Exterior Evaluation : B
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Seat - Cut, Crack - Small / (L) Front Trim - Grime - Minimal / Carpet - Worked - Minimal / (L) Front Floor Mat - Worked - Small	**Remarks** Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire and jack, with warranty booklet and tools, visible hairlines scratches on vehicle