BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 27, Jul, 2026 14:59

Make	Isuzu	**Model**	NLR77
YOM	2021	**Odo Meter Reading**	154,271
Registration No.	NGA9469	**Chassis No.**	PABNLR77HL2000254
CC	3.0	**Transmission**	M/T
Fuel Type	Diesel	**Type of Body**	Aluminum Van
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**55.9**	49	56	63
2	Boot Lid	**21.3**	23	21	20
3	Roof	**83.0**	89	76	101/66
4	Left Front Fender	**83.4**	73	77	101
5	Left Front Door	**68.3**	58	54	93
6	Center Panel Left	**80.7**	88	80	74
7	Left Rear Door				
8	Left Back Panel	**17.3**	19	19	15
9	Right Front Fender	**69.0**	79	63	65
10	Right Front Door	**62.1**	66	58	62
11	Center Panel Right	**70.1**	66	72	72
12	Right Rear Door				
13	Right Back Panel	**63.4**	93	36	61

Overall Evaluation : D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : D	Exterior Evaluation : E
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Sunvisor, Sunglass Holder - Grime - Large / Steering Wheel - Worn, Peel, Crack - Large / (L) Front Trim - Loose, Deformed - Medium / (L) Front Floor Mat - Missing - Yes / Carpet - Worked - Minimal / Dashboard - Loose, Deformed - Large / (R) Front Trim - Loose, Deformed - Medium	**Remarks** (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Center Panel - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Rear Gate - Scratch & Dent - Large / Roof - Scratch & Dent - Large / Cargo Bed Floor - Rust, Corrosion - Large / Cab Back Panel - Crack, Gap - Medium / (L) Side Gate - Scratch & Dent - Large / (L) Center Panel - Scratch - Minimal / (L) Side Window - Damaged - Large / (L) Front Door, Molding - Scratch & Dent - Large / (R) Front Tyre - Crack, Cut - Yes / (R) Rear Tyre - Crack, Cut - Yes / (L) Front Fender, Molding - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Front Panel - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : D**
Remarks Defects not found	**Remarks** Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With Lto plate, 1key, no warranty booklet and tools, no spare tire and jack, rear gate issue,Worn tires, left window issue,aircon issue,