Grading Report

General Information

Date & Time: 16, Nov, 2024 13:39

Make	Toyota	**Model**	Vios
YOM	2024	**Mileage**	9,693
Registration No.	NKC6810	**Chassis No.**	PA1B18F34R4254004
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**134.0**	126	138	138
2	Boot Lid	**140.3**	132	144	145
3	Roof	**130.5**	135	137	130/120
4	Left Front Fender	**116.6**	117	112	121
5	Left Front Door	**122.6**	126	124	118
6	Center Panel Left				
7	Left Rear Door	**121.6**	127	126	112
8	Left Back Panel	**133.3**	139	132	129
9	Right Front Fender	**124.3**	129	123	121
10	Right Front Door	**124.3**	130	122	121
11	Center Panel Right				
12	Right Rear Door	**131.3**	118	127	149
13	Right Back Panel	**133.0**	132	135	132

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Grading Report

Interior Evaluation : A	Exterior Evaluation : A
	
a : Cut, Fray **d** : Loose, Deformed **k** : Animal Hair **s** : Smell **t** : Cigarette Burns **x** : Defective **y** : Stain	**A** : Scratch **AU** : Scratch & Dent **B** : Modified **C** : Corrosion **G** : Stone chip **P** : Faded **S** : Rust **SC** : Rust & Corrosion **U** : Dent **X** : Defective **Y** : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small	**Remarks** (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Defects not found

Inspector Notes
repainted bumper/incomplete tools/jack/with spare tire/no warranty booklets