BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 25, Nov, 2024 09:59

Make	Toyota	**Model**	Vios
YOM	2023	**Mileage**	6,436
Registration No.	NHI8760	**Chassis No.**	PA1B18F32P4213559
CC	1.3	**Transmission**	M/T
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**104.1**	107	99	107
2	Boot Lid	**102.6**	100	101	107
3	Roof	**101.0**	112	90	99/103
4	Left Front Fender	**94.8**	97	98	89
5	Left Front Door	**93.7**	94	94	93
6	Center Panel Left				
7	Left Rear Door	**106.0**	106	110	102
8	Left Back Panel	**106.0**	108	110	100
9	Right Front Fender	**95.5**	95	97	95
10	Right Front Door	**93.5**	93	92	96
11	Center Panel Right				
12	Right Rear Door	**102.6**	105	102	101
13	Right Back Panel	**99.2**	99	95	103

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : A
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small	**Remarks** Bonnet, Headlight - Dent - Small / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : C**
Remarks Defects not found	**Remarks** Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
dirtmarks at the trunk floor. hairline scratches around the exterior. no user manual. With warranty booklet and tools.