Grading Report

General Information

Date & Time: 23, Nov, 2024 15:40

Make	Toyota	**Model**	Vios
YOM	2024	**Mileage**	49,515
Registration No.	DBJ7185	**Chassis No.**	PA1B18F31P4226643
CC	1.3	**Transmission**	M/T
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**114.0**	116	113	113
2	Boot Lid	**104.0**	102	104	106
3	Roof	**103.7**	106	100	100/109
4	Left Front Fender	**103.6**	100	105	106
5	Left Front Door	**124.3**	108	142	123
6	Center Panel Left				
7	Left Rear Door	**118.0**	142	111	101
8	Left Back Panel	**110.3**	118	111	102
9	Right Front Fender	**101.2**	108	96	100
10	Right Front Door	**96.8**	103	91	96
11	Center Panel Right				
12	Right Rear Door	**102.8**	97	102	110
13	Right Back Panel	**103.5**	96	103	112

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Grading Report

Interior Evaluation : B	Exterior Evaluation : C
	
a : Cut, Fray **d** : Loose, Deformed **k** : Animal Hair **s** : Smell **t** : Cigarette Burns **x** : Defective **y** : Stain	**A** : Scratch **AU** : Scratch & Dent **B** : Modified **C** : Corrosion **G** : Stone chip **P** : Faded **S** : Rust **SC** : Rust & Corrosion **U** : Dent **X** : Defective **Y** : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium	**Remarks** (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
with spare tire/jack/warranty booklets/incomplete tools/no reverse camera