BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 25, Nov, 2024 08:49

Make	Toyota	**Model**	Vios
YOM	2023	**Mileage**	5,018
Registration No.	DAS8312	**Chassis No.**	PA1B18F35N419115
CC	1.3	**Transmission**	M/T
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**93.8**	88	104	90
2	Boot Lid	**98.7**	100	96	100
3	Roof	**91.8**	95	87	94/92
4	Left Front Fender	**98.3**	101	98	96
5	Left Front Door	**97.5**	97	99	96
6	Center Panel Left				
7	Left Rear Door	**98.3**	100	100	95
8	Left Back Panel	**106.6**	117	103	100
9	Right Front Fender	**98.6**	100	100	97
10	Right Front Door	**98.3**	95	100	100
11	Center Panel Right				
12	Right Rear Door	**102.0**	106	100	100
13	Right Back Panel	**99.0**	99	97	101

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : A
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	**Remarks** Bonnet - Repair Traces - Yes / (L) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Bonnet/Hood had been replaced. adhesive mark at the left side mirror. swirlmarks and hairline scratches around the exterior.With warranty booklet and user manual. no tools.