BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 23, Nov, 2024 13:49

Make	Toyota	**Model**	Vios
YOM	2024	**Mileage**	6,287
Registration No.	CCA7581	**Chassis No.**	PA1B18F30R4256803
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**117.3**	117	119	116
2	Boot Lid	**121.0**	131	116	116
3	Roof	**104.6**	110	111	98/100
4	Left Front Fender	**106.6**	107	109	104
5	Left Front Door	**101.7**	106	97	102
6	Center Panel Left				
7	Left Rear Door	**108.6**	115	111	100
8	Left Back Panel	**118.0**	130	123	101
9	Right Front Fender	**112.0**	112	117	107
10	Right Front Door	**97.7**	97	96	100
11	Center Panel Right				
12	Right Rear Door	**102.3**	94	100	113
13	Right Back Panel	**105.3**	104	105	107

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : B	Exterior Evaluation : B
 **a** : Cut, Fray **d** : Loose, Deformed **k** : Animal Hair **s** : Smell **t** : Cigarette Burns **x** : Defective **y** : Stain	 **A** : Scratch **AU** : Scratch & Dent **B** : Modified **C** : Corrosion **G** : Stone chip **P** : Faded **S** : Rust **SC** : Rust & Corrosion **U** : Dent **X** : Defective **Y** : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Small	**Remarks** (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
swirlmarks and hairline scratches around the exterior. with warranty booklet, user manual and tools.