BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 25, Nov, 2024 10:06

Make	Toyota	**Model**	Vios
YOM	2023	**Mileage**	100,097
Registration No.	DBH7852	**Chassis No.**	PA1B18F31P4209938
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**107.6**	107	109	107
2	Boot Lid	**77.6**	76	73	85
3	Roof	**96.2**	100	97	88/100
4	Left Front Fender	**110.3**	99	130	102
5	Left Front Door	**98.2**	98	97	100
6	Center Panel Left				
7	Left Rear Door	**109.8**	121	111	98
8	Left Back Panel	**107.8**	122	104	97
9	Right Front Fender	**97.1**	100	86	106
10	Right Front Door	**104.1**	100	119	93
11	Center Panel Right				
12	Right Rear Door	**102.8**	96	100	113
13	Right Back Panel	**100.0**	94	89	117

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T
VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : B	Exterior Evaluation : C
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium	**Remarks** (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Dent - Minimal
Frame Evaluation : C	**Functional Evaluation : A**
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	**Remarks** Defects not found

Inspector Notes

with spare tire/tools/jack/ no warranty booklets/no reverse camera