BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 17:37

Make	Toyota	**Model**	Vios
YOM	2021	**Mileage**	44,607
Registration No.	CBM6767	**Chassis No.**	PA1B18F32M4145582
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**331.6**	333	170	492
2	Boot Lid	**104.6**	105	103	106
3	Roof	**97.2**	102	99	91/98
4	Left Front Fender	**94.5**	112	94	78
5	Left Front Door	**97.8**	100	91	103
6	Center Panel Left				
7	Left Rear Door	**101.0**	105	93	105
8	Left Back Panel	**101.2**	106	98	100
9	Right Front Fender	**249.3**	138	402	208
10	Right Front Door	**93.1**	89	102	88
11	Center Panel Right				
12	Right Rear Door	**90.5**	91	88	93
13	Right Back Panel	**99.3**	98	94	106

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Grading Report

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small	**Remarks** (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with spare tire and jack/warranty booklets/no tools/hairline scratches around the vehicle