BLUE-T VEHICLE GRADING SYSTEM

# Grading Report

## General Information

**Date & Time: 03, Dec, 2024 15:28**

| | | | |
|---|---|---|---|
| **Make** | Toyota | **Model** | Vios |
| **YOM** | 2021 | **Mileage** | 48,627 |
| **Registration No.** | CAW1765 | **Chassis No.** | PA1B18F33M4154212 |
| **CC** | 1.3 | **Transmission** | CVT |
| **Fuel Type** | Gas | **Type of Body** | Sedan |
| **Colour** | Blue | | |

## Body / Panel Condition




| # | Area | Thickness(um) | | | |
|---|---|---|---|---|---|
| | | Average | Value1 | Value2 | Value3/4 |
| 1 | Bonnet | **104.3** | 110 | 95 | 108 |
| 2 | Boot Lid | **108.0** | 104 | 97 | 123 |
| 3 | Roof | **90.9** | 89 | 81 | 100/94 |
| 4 | Left Front Fender | **94.1** | 90 | 97 | 95 |
| 5 | Left Front Door | **100.7** | 101 | 99 | 102 |
| 6 | Center Panel Left | | | | |
| 7 | Left Rear Door | **100.0** | 106 | 102 | 92 |
| 8 | Left Back Panel | **103.7** | 97 | 104 | 110 |
| 9 | Right Front Fender | **161.6** | 167 | 156 | 162 |
| 10 | Right Front Door | **150.6** | 157 | 142 | 153 |
| 11 | Center Panel Right | | | | |
| 12 | Right Rear Door | **98.2** | 94 | 96 | 105 |
| 13 | Right Back Panel | **100.9** | 99 | 98 | 106 |

## Overall Evaluation : A

**Disclaimer**

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

# Grading Report

| Interior Evaluation : B | Exterior Evaluation : B |
|---|---|
| <br>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain | <br>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap |
| **Remarks**<br>Mat Other - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium | **Remarks**<br>(R) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Roof - Dent - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small |
| **Frame Evaluation : A** | **Functional Evaluation : A** |
| **Remarks**<br>Defects not found | **Remarks**<br>Spare Key - Issue - Unexist |

| Inspector Notes |
|---|
| no tools, coin holder can't close |