BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 13:47

Make	Toyota	**Model**	Vios
YOM	2021	**Mileage**	37,041
Registration No.	NGO9432	**Chassis No.**	PA1B18F34M4137001
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**110.6**	111	103	118
2	Boot Lid	**112.1**	124	99	114
3	Roof	**92.4**	103	87	89/91
4	Left Front Fender	**113.6**	154	95	92
5	Left Front Door	**93.1**	85	100	94
6	Center Panel Left				
7	Left Rear Door	**93.7**	99	85	98
8	Left Back Panel	**110.0**	114	108	108
9	Right Front Fender	**99.0**	104	100	93
10	Right Front Door	**100.7**	99	96	107
11	Center Panel Right				
12	Right Rear Door	**93.5**	92	93	97
13	Right Back Panel	**98.8**	94	98	105

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Small	**Remarks** (R) Front Fender, Molding - Dent - Minimal / (R) Front Tyre - Crack, Cut - Yes / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Fender, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
no reverse camera, spare tire damage, no tools and jack