BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 10:47

Make	Toyota	**Model**	Vios
YOM	2021	**Mileage**	46,146
Registration No.	NGU4446	**Chassis No.**	PA1B18F33M4137667
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**110.3**	108	104	119
2	Boot Lid	**101.3**	101	103	100
3	Roof	**92.5**	100	88	89/94
4	Left Front Fender	**94.8**	96	94	94
5	Left Front Door	**92.2**	92	98	87
6	Center Panel Left				
7	Left Rear Door	**87.0**	90	86	84
8	Left Back Panel	**104.6**	111	101	102
9	Right Front Fender	**124.3**	120	126	127
10	Right Front Door	**82.8**	86	80	83
11	Center Panel Right				
12	Right Rear Door	**85.5**	87	83	86
13	Right Back Panel	**195.3**	169	174	243

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium	**Remarks** (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Replaced - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

siwrlmarks and hairline scratches around the exterior. without warranty booklet and tools. with user manual. cable of dashcam left in the vehicle.