BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 10:02

Make	Toyota	**Model**	Vios
YOM	2021	**Mileage**	21,632
Registration No.	DAV9684	**Chassis No.**	PA1B18F31M4155391
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**108.0**	105	103	116
2	Boot Lid	**100.8**	100	101	102
3	Roof	**100.4**	112	89	92/109
4	Left Front Fender	**99.5**	98	100	101
5	Left Front Door	**94.3**	100	95	89
6	Center Panel Left				
7	Left Rear Door	**94.5**	96	95	93
8	Left Back Panel	**113.0**	120	109	110
9	Right Front Fender	**96.5**	97	98	94
10	Right Front Door	**91.7**	90	91	95
11	Center Panel Right				
12	Right Rear Door	**95.8**	94	93	101
13	Right Back Panel	**98.9**	95	98	103

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Small	**Remarks** Rear Bumper, Lamps, Panels - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Dent - Minimal / (L) Front Door, Molding - Dent - Minimal
Frame Evaluation : A	**Functional Evaluation : B**
Remarks Defects not found	**Remarks** Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
hairline scratches around the exterior.