BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 10:36

Make	Toyota	**Model**	Wigo
YOM	2023	**Mileage**	18,213
Registration No.	DBJ7191	**Chassis No.**	MHKAA1BC2PJ004334
CC	1.0	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Hatchback
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**108.0**	108	106	110
2	Boot Lid	**77.3**	79	81	72
3	Roof	**80.2**	74	79	94/74
4	Left Front Fender	**83.6**	86	86	79
5	Left Front Door	**97.0**	92	95	104
6	Center Panel Left				
7	Left Rear Door	**91.7**	98	96	81
8	Left Back Panel	**84.1**	80	86	86
9	Right Front Fender	**81.6**	83	89	74
10	Right Front Door	**93.5**	99	95	87
11	Center Panel Right				
12	Right Rear Door	**90.5**	84	87	100
13	Right Back Panel	**94.5**	86	87	111

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small	**Remarks** Bonnet, Headlight - Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Front Fender, Molding - Dent - Small / (L) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Defects not found

Inspector Notes
with warranty booklets/jack/tools incomplete/no spare tire