BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 07:28

Make	Toyota	**Model**	Vios
YOM	2024	**Mileage**	16,675
Registration No.	NFS6715	**Chassis No.**	PA1B18F32P4236887
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**188.6**	193	182	191
2	Boot Lid	**214.6**	207	232	205
3	Roof	**177.7**	181	177	172/181
4	Left Front Fender	**167.0**	169	161	171
5	Left Front Door	**162.0**	167	158	161
6	Center Panel Left				
7	Left Rear Door	**160.0**	164	158	158
8	Left Back Panel	**165.6**	162	173	162
9	Right Front Fender	**195.6**	214	188	185
10	Right Front Door	**188.3**	187	182	196
11	Center Panel Right				
12	Right Rear Door	**180.6**	172	176	194
13	Right Back Panel	**182.3**	165	184	198

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small	**Remarks** (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Dent - Small / (R) Step, In-panel, Side Spoiler - Dent - Small / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Defects not found

Inspector Notes
with spare tire/tools/jack/warranty booklets/ no reverse camera