BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 16:41

Make	Toyota	**Model**	Vios
YOM	2022	**Mileage**	18,591
Registration No.	DAQ8791	**Chassis No.**	PA1B18F37N4179812
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**110.3**	119	102	110
2	Boot Lid	**114.0**	126	104	112
3	Roof	**97.2**	100	96	95/98
4	Left Front Fender	**100.9**	98	102	103
5	Left Front Door	**112.6**	110	118	110
6	Center Panel Left				
7	Left Rear Door	**110.0**	114	107	109
8	Left Back Panel	**113.6**	136	105	100
9	Right Front Fender	**93.8**	96	95	91
10	Right Front Door	**98.3**	104	95	96
11	Center Panel Right				
12	Right Rear Door	**98.6**	100	87	109
13	Right Back Panel	**99.0**	92	97	108

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : C	Exterior Evaluation : B
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Cigarette Burns - Burnt, Hole	**Remarks** Rear Bumper, Lamps, Panels - Dent - Minimal / (L) Rear Fender, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Small / Roof - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Dent - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
no reverse camera/no spare tire/no tools and jack/no warranty booklets