BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 15:38

Make	Toyota	**Model**	Vios
YOM	2023	**Mileage**	41,038
Registration No.	NIM5984	**Chassis No.**	PA1B18F3XP4213714
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**109.0**	115	103	109
2	Boot Lid	**105.6**	103	106	108
3	Roof	**106.2**	118	102	102/103
4	Left Front Fender	**96.2**	98	96	95
5	Left Front Door	**104.8**	111	100	104
6	Center Panel Left				
7	Left Rear Door	**114.0**	121	112	109
8	Left Back Panel	**111.6**	118	111	106
9	Right Front Fender	**95.7**	93	99	95
10	Right Front Door	**92.1**	92	90	95
11	Center Panel Right				
12	Right Rear Door	**100.7**	98	99	105
13	Right Back Panel	**225.6**	238	237	202

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Small	**Remarks** (R) Step - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Fender - Replaced - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Rust, Corrosion - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Mirror - Scratch - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Reverse Camera - N/A - Yes

Inspector Notes
hairline scratches around the exterior. without warranty booklet and user manual.