BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 17:40

Make	Toyota	**Model**	Wigo
YOM	2021	**Mileage**	23,488
Registration No.	DAV5135	**Chassis No.**	MHKA4DF5FMJ055933
CC	1.0	**Transmission**	A/T
Fuel Type	Gas	**Type of Body**	Hatchback
Colour	Gray		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**102.0**	105	103	98
2	Boot Lid	**89.3**	83	92	93
3	Roof	**84.3**	74	87	93/82
4	Left Front Fender	**97.9**	92	96	106
5	Left Front Door	**90.8**	89	92	92
6	Center Panel Left				
7	Left Rear Door	**90.2**	96	90	85
8	Left Back Panel	**92.7**	89	104	86
9	Right Front Fender	**97.4**	102	101	89
10	Right Front Door	**96.2**	91	97	101
11	Center Panel Right				
12	Right Rear Door	**93.3**	94	93	93
13	Right Back Panel	**92.4**	94	87	97

Overall Evaluation : A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Loose, Deformed - Large	**Remarks** (L) Front Fender - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
Left front fender was replace