BLUE-T VEHICLE GRADING SYSTEM

Grading Report

General Information

Date & Time: 03, Dec, 2024 18:46

Make	Toyota	**Model**	Vios
YOM	2021	**Mileage**	25,511
Registration No.	NGR5690	**Chassis No.**	PA1B18F3XL4129192
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**106.4**	94	120	105
2	Boot Lid	**101.8**	100	100	106
3	Roof	**90.7**	92	88	89/94
4	Left Front Fender	**87.6**	90	80	94
5	Left Front Door	**91.8**	90	95	91
6	Center Panel Left				
7	Left Rear Door	**94.8**	102	96	86
8	Left Back Panel	**98.0**	102	99	94
9	Right Front Fender	**91.7**	94	89	92
10	Right Front Door	**92.7**	90	94	95
11	Center Panel Right				
12	Right Rear Door	**90.3**	86	90	95
13	Right Back Panel	**94.7**	92	94	99

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : A	Exterior Evaluation : E
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small	**Remarks** Rear Bumper, Lamps, Panels - Dent - Large / Trunk Hood, Rear Gate - Dent - Large / (L) Step, In-panel, Side Spoiler - Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	**Functional Evaluation : A**
Remarks Defects not found	**Remarks** Spare Key - Issue - Unexist

Inspector Notes
with spare tire and jack/fuel lid loose/no tools and warranty booklets/ no reverse camera