

General Information

Date & Time: 03, Mar, 2025 10:02

Make	Toyota	Model	Vios
YOM	2024	Mileage	20,834
Registration No.	CCC9238	Chassis No.	PA1B18F35R4255971
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	139.6	141	139	139
2	Boot Lid	121.3	118	126	120
3	Roof	121.7	129	136	113/109
4	Left Front Fender	124.6	130	121	123
5	Left Front Door	123.3	125	123	122
6	Center Panel Left				
7	Left Rear Door	132.3	150	122	125
8	Left Back Panel	119.3	128	122	108
9	Right Front Fender	137.3	142	136	134
10	Right Front Door	84.2	92	84	77
11	Center Panel Right				
12	Right Rear Door	102.3	99	97	111
13	Right Back Panel	111.0	104	111	118

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Dent - Minimal / Roof - Dent - Small / (L) Rear Fender, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Turn Signal, Hazard Flasher - Issue - Yes

Inspector Notes
with LTO plate/with spare tire/with jack and tools/with warranty booklet/ left tail light crack