

General Information

Date & Time: 22, Jul, 2026 07:42

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	6,090
Registration No.	DBS4022	Chassis No.	MHFAB1BY9R3119771
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	102	97	110
2	Boot Lid	101.6	91	118	96
3	Roof	118.2	129	122	104/118
4	Left Front Fender	104.6	108	101	105
5	Left Front Door	119.3	111	121	126
6	Center Panel Left				
7	Left Rear Door	113.0	122	109	108
8	Left Back Panel	118.0	126	113	115
9	Right Front Fender	101.2	105	101	98
10	Right Front Door	119.3	124	120	114
11	Center Panel Right				
12	Right Rear Door	117.0	115	114	122
13	Right Back Panel	120.3	107	123	131

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (R) Front Floor Mat - Missing - Yes / (R) Front Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Missing - Yes / (L) Front Seat - Grime - Minimal / Ceiling - Grime - Minimal	Remarks (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with warranty booklet/with tools and jack/with spare tire/no spare key/maintenance warning lamp on/hairline scratches on the body/possible pest inside