

## General Information

Date & Time: 22, Jul, 2026 07:54

|                  |            |                   |                   |
|------------------|------------|-------------------|-------------------|
| Make             | Mitsubishi | Model             | Mirage            |
| YOM              | 2025       | Odo Meter Reading | 9,661             |
| Registration No. | NKQ8298    | Chassis No.       | PAEA13RJSSA011043 |
| CC               | 1.2        | Transmission      | CVT               |
| Fuel Type        | Gas        | Type of Body      | Sedan             |
| Colour           | Red        |                   |                   |

## Body / Panel Condition



| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 127.0         | 133    | 127    | 121      |
| 2  | Boot Lid           | 108.3         | 103    | 110    | 112      |
| 3  | Roof               | 105.2         | 107    | 102    | 106/106  |
| 4  | Left Front Fender  | 107.3         | 105    | 108    | 109      |
| 5  | Left Front Door    | 107.3         | 111    | 104    | 107      |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 105.3         | 109    | 106    | 101      |
| 8  | Left Back Panel    | 112.3         | 114    | 114    | 109      |
| 9  | Right Front Fender | 107.0         | 115    | 105    | 101      |
| 10 | Right Front Door   | 114.6         | 119    | 110    | 115      |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 112.3         | 110    | 110    | 117      |
| 13 | Right Back Panel   | 114.6         | 111    | 113    | 120      |

## Overall Evaluation :

C

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| Interior Evaluation :                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | D | Exterior Evaluation :                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | D |
| <p>The diagram shows the interior of a vehicle from a top-down perspective. Numbered areas include: 1 (Dashboard), 2 (Front Passenger Seat Back), 3 (Center Console), 4 (Rear Passenger Seat Back), 5 (Rear Driver Seat Back), 6 (Rear Right Side Panel), 7 (Rear Center Console), 8 (Trunk Area), 9 (Front Driver Seat Back), and 10 (Left Side Door Panel). Lettered codes include: D (Front Passenger Seat Headrest), D2 (Four locations on side door panels), Y3 (Two locations on rear seat headrests), and D2 (Two locations on front seat headrests).</p> |   | <p>The diagram shows three views of the exterior of a vehicle. The left view (driver's side) includes numbers 6-10 and codes A3, A2, A1. The middle view (front) includes numbers 11-15 and codes A2, A1. The right view (passenger's side) includes numbers 1-5 and codes AU4, A1, A3, A2, U1.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |   |
| <b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain                                                                                                                                                                                                                                                                                                                                                                                                         |   | <b>A</b> : Scratch <b>AU</b> : Scratch & Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust & Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |   |
| <b>Remarks</b><br>(L) Front Seat - Worn - Yes / (L) Rear Trim - Worked - Small / (R) Rear Trim - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Medium / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small / Mat Other - Worked - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium                                                                                                                             |   | <b>Remarks</b><br>(R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small |   |
| Frame Evaluation :                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | A | Functional Evaluation :                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | A |
| <b>Remarks</b><br>Defects not found                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |   | <b>Remarks</b><br>Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |   |

## Inspector Notes

with lto plate/without warranty booklet/with spare tire/with dent and scratches on the body/without spare key/without tools and jack