

General Information

Date & Time: 22, Jul, 2026 15:44

Make	Toyota	Model	Innova
YOM	2005	Odo Meter Reading	75,931
Registration No.	XTR813	Chassis No.	KUN405000067
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.4	75	108	76
2	Boot Lid	243.6	256	238	237
3	Roof	72.7	69	80	74/68
4	Left Front Fender	171.0	171	167	175
5	Left Front Door	131.0	134	124	135
6	Center Panel Left				
7	Left Rear Door	124.6	133	118	123
8	Left Back Panel	133.0	140	132	127
9	Right Front Fender	133.6	129	133	139
10	Right Front Door	130.6	140	127	125
11	Center Panel Right				
12	Right Rear Door	125.6	125	121	131
13	Right Back Panel	133.6	128	127	146

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Large / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small / Sunvisor, Sunglass Holder - Grime - Medium / Overall Interior - Worn as per age - Yes	Remarks (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Overall Exterior - Faded(Color, Gloss) - Yes / (L) Front Fender, Molding - Crack, Gap - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Seat Belts - Issue - Yes

Inspector Notes
with LTO plate/with warranty booklet/with tools and jack/with spare tire/no fog lights/park light issue/seat belt issue/plate light issue/scratches on taillight and headlight cover/faded color/hairline scratches on the body/stereo volume switch issue/with spare key/with seat cover