

General Information

Date & Time: 22, Jul, 2026 15:49

Make	Mercedes-Benz	Model	ML 350 CDI
YOM	2013	Odo Meter Reading	49,842
Registration No.	UAQ637	Chassis No.	WDC1660231A165540
CC	3.0	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.9	102	91	107
2	Boot Lid	135.3	129	134	143
3	Roof	158.2	151	129	175/178
4	Left Front Fender	101.9	91	107	108
5	Left Front Door	144.0	143	152	137
6	Center Panel Left				
7	Left Rear Door	152.0	152	162	142
8	Left Back Panel	134.3	135	132	136
9	Right Front Fender	112.3	116	117	104
10	Right Front Door	142.0	137	143	146
11	Center Panel Right				
12	Right Rear Door	148.3	135	156	154
13	Right Back Panel	130.0	129	130	131

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Inspector Notes
Plate can't verify, aircon issue, leaking issue in low or high side line, other button is not responsive/faulty, rear signal light issue, intake hoses issue, mild white smoke and foul smell in exhaust, with spare tire and key, with tools, radiator hose issue, scratches in taillight and headlight, minor scratches and dent on exterior. abs indicator lamp on, battery key issue.