

General Information

Date & Time: 21, Jul, 2026 16:10

Make	Toyota	Model	Hiace
YOM	2025	Odo Meter Reading	61,650
Registration No.	GBK3012	Chassis No.	JTFNAFAP4S8059081
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	106	129	143
2	Boot Lid	100.7	97	102	103
3	Roof	121.2	116	155	123/91
4	Left Front Fender	106.3	108	106	105
5	Left Front Door	114.3	119	113	111
6	Center Panel Left	126.0	131	124	123
7	Left Rear Door	103.6	106	104	101
8	Left Back Panel	100.7	110	95	98
9	Right Front Fender	109.3	109	107	112
10	Right Front Door	106.6	106	108	106
11	Center Panel Right	122.0	124	118	124
12	Right Rear Door	111.6	110	112	113
13	Right Back Panel	106.3	110	102	107

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Minimal / Rear Seat - Grime - Medium / Ceiling - Crinkle - Large	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Horn - Issue - Yes

Inspector Notes

With LTO plate, with warranty booklet, with tools, with jack, no seat cover, with spare key 2pcs, with spare tire, with hairline scratches, horn not functioning.