

General Information

Date & Time: 22, Jul, 2026 15:40

Make	Toyota	Model	Hiace
YOM	2018	Odo Meter Reading	398,246
Registration No.	NAQ1558	Chassis No.	JTFJT02P0J5016152
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	146.3	152	147	140
2	Boot Lid	113.3	114	116	110
3	Roof	109.2	107	104	102/124
4	Left Front Fender	139.3	134	131	153
5	Left Front Door	122.0	118	124	124
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	110.6	112	109	111
9	Right Front Fender	140.6	129	153	140
10	Right Front Door	112.3	112	111	114
11	Center Panel Right	113.6	120	115	106
12	Right Rear Door	113.6	119	108	114
13	Right Back Panel	110.3	115	106	110

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Cut, Crack - Large / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Seat - Worn - Yes / Rear Seat - Worn - Yes / Ceiling - Grime - Large / Mat Other - Worked - Small / (R) Front Trim - Worked - Small / Overall Interior - Worn as per age - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Minimal / (R) Rear Trim - Worked - Small / (L) Rear Trim - Worked - Small / Sunvisor, Sunglass Holder - Grime - Medium	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Center Panel - Scratch - Minimal / (R) Rear Door, Molding - Repair mark - Difference in Color / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Repair mark - Difference in Color / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / Front Panel - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Roof - Dent - Small / Overall Exterior - Worn as per age - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Shift Shock - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/with warranty booklet/with jack no tools/with spare tire/with dent and hairlines scratches on the body/without spare key/engine unusual noise/without reverse camera/worn tires/reverse light issue