

General Information

Date & Time: 03, Mar, 2025 16:53

Make	Toyota	Model	Vios
YOM	2021	Mileage	47,968
Registration No.	NGO8362	Chassis No.	PA1B18F31M4135415
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	104	107	111
2	Boot Lid	102.0	100	106	100
3	Roof	97.4	103	93	93/101
4	Left Front Fender	88.8	92	90	84
5	Left Front Door	91.0	93	93	87
6	Center Panel Left				
7	Left Rear Door	98.0	100	100	95
8	Left Back Panel	98.6	100	99	97
9	Right Front Fender	90.5	87	91	93
10	Right Front Door	95.2	95	97	94
11	Center Panel Right				
12	Right Rear Door	100.2	100	101	100
13	Right Back Panel	93.7	95	93	93

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : D	Functional Evaluation : B
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside (Rear Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside (Rear Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Retractable Mirror - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

crack left taillight. Large Gap at front bumper and right front fender. with warranty booklet, spare tire, jack but incomplete tools. with LTO plate.