

General Information

Date & Time: 24, Jul, 2026 15:48

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	84,685
Registration No.	NJC4366	Chassis No.	MHFAA1BY0S0042489
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	113	109	112
2	Boot Lid	110.6	104	108	120
3	Roof	116.0	121	119	112/112
4	Left Front Fender	98.6	100	99	97
5	Left Front Door	120.6	116	119	127
6	Center Panel Left				
7	Left Rear Door	118.3	115	114	126
8	Left Back Panel	130.6	150	106	136
9	Right Front Fender	102.2	104	108	95
10	Right Front Door	113.6	118	116	107
11	Center Panel Right				
12	Right Rear Door	114.0	120	106	116
13	Right Back Panel	119.0	109	117	131

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Minimal / Mat Other - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Minimal / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Medium
Frame Evaluation : A Remarks Defects not found	Functional Evaluation : B Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

with Ito plate/with warranty booklet/with spare tire/with tools and jack/with reverse camera/with dent and scratches on the body/without spare key