

General Information

Date & Time: 24, Jul, 2026 15:47

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	15,320
Registration No.	NJQ6543	Chassis No.	MHFAA1BY1S0045692
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	118	117	122
2	Boot Lid	112.0	107	111	118
3	Roof	120.5	126	132	112/112
4	Left Front Fender	110.0	120	103	107
5	Left Front Door	122.0	121	120	125
6	Center Panel Left				
7	Left Rear Door	124.6	122	131	121
8	Left Back Panel	135.0	134	120	151
9	Right Front Fender	107.6	114	111	98
10	Right Front Door	116.6	123	115	112
11	Center Panel Right				
12	Right Rear Door	114.6	123	110	111
13	Right Back Panel	119.6	117	118	124

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Worked - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Rear Seat - Grime - Medium / Ceiling - Grime - Medium / Mat Other - Grime - Minimal	Remarks (R) Front Fender, Molding - Crack, Gap - Large / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Crack, Gap - Large / Front Bumper, Grille, Lamps - Dent - Large / Bonnet, Headlight - Dent - Large / Member (Bolted) - Dent - Yes / Roof - Scratch - Minimal
Frame Evaluation : C	Functional Evaluation : C
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Air Conditioner - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
with Ito plate/with warranty booklet/with spare tire/with reverse camera/with jack and tools/with dent and scratches on the body/with air-conditioned issue